#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012132 Address: 333 Burma Road **Date Inspected:** 07-Feb-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes NA No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

**Bridge No:** 34-0006 **Component: OBG** and Tower

**Summary of Items Observed:** 

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. This QA Inspector observed the following:

**OBG** Trial Assembly

This QA Inspector observed ZPMC welders have left rolls of flux cored welding electrodes on two welding machines located inside the west bound cross beam side of the OBG between panel points 52 and 53. It appears that the welding machines had been used to perform splice welding of "T" stiffeners during the dayshift. No ZPMC QC Inspectors or other ZPMC workers were observed to be in the area and this QA Inspector informed dayshift Caltrans QA Inspectors' to contact dayshift ZPMC QC personnel to ensure these welding electrodes are not used for any additional welding of Caltrans materials. See the photograph below for additional information.

OBG Bays 1 through 9

This QA Inspector observed no ZPMC personnel were working on Caltrans OBG segments or tower assemblies in OBG Bays 1 through 9.

OBG Bays 13 and 14

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed no ZPMC personnel were working on Caltrans OBG segments or tower assemblies in OBG Bays 13 or 14.

## Heavy Dock Tower

This QA Inspector observed ZPMC personnel have positioned a 400 ton capacity floating crane adjacent to the heavy dock and ZPMC workers are installing heavy duty rigging to one of the crane hooks in preparation for installing East tower lift 2 on top of East tower lift 1. ZPMC has installed a wooden ramp/platform which is intended to provide a cushion the bottom of the East tower lift 2 when it is moved from a horizontal position to a vertical position. Later in the shift this QA Inspector observed ZPMC has rotated the East tower lift 2 from the horizontal position to the vertical position and the East tower lift 2 is hanging from the crane hook. It appears that ZPMC intends to install this East tower lift 2 on top of East tower lift 1 during daylight hours. This QA Inspector observed no production welding taking place on any of the heavy dock tower assemblies. See the photograph below for additional information.





### **Summary of Conversations:**

See Above.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang phone: 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Dawson,Paul	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer